

# ***SSP-ACC-DRILLSHIELD-038* USER MANUAL**

**DISCLAIMER: Always wear safety goggles, work gloves, and proper safety equipment when using this tool. Follow all safety rules provided by your tool manufacturer!**

1. **SELECT** a 3/8" shank drill bit that passes at least a 1/2 inch past the Shield's ball bearing assembly. (If your drill bit passes through at less than 1/2 inch, DO NOT USE IT. Consider it incompatible, and unsafe to use. Your drill may not be able to grab it properly & would be dangerous to use!)
2. **IF YOUR BIT CLEARS BY 1/2 INCH AS RECOMMENDED:** Slide it through the ball bearing assembly. Note: Tool Manufacturer tolerances vary, and we cannot guarantee fit for every 3/8" shank.
3. **ATTACH THE SHANK** to your drill chuck. Ensure a tight & proper mating.
4. **OPERATE YOUR DRILL**, carefully observing through the Drill Shield's transparent cup design.  
**Warning:** The Drill Shield may not capture all expelled debris! Wear preventative safety equipment and watch out for projectiles that might exit.
5. **ONCE COMPLETED DRILLING**, empty out the debris contents into a trash bin. (They may be hot!)
6. **PROPER MAINTENANCE AND CARE:** Use a small brush to completely remove all remaining debris from the Drill Shield. Do not attempt to remove or open the ball bearing assembly for any reason.